

### FREIGHTLINER CENTURY / COLUMBIA / CORONADO CONDO / MID-ROOF VISORS.

With 3 side bolts per side. Add an "L" after your part number to order a louvered visor. Ex: 25320L. Does not replace stainless steel day cab visor. (Kit)

#### 17" DROP VISOR (2004 & NEWER)

|    |                           |           |            |
|----|---------------------------|-----------|------------|
|    | Blank (0)                 | 25560     | N25560     |
|    | Supernova (8)             | 25561     | N25561     |
|    | Crew (8)                  | 25563     | N25563     |
|    | 2" Round Flat (10)        | 25564B    | N25564B    |
|    | 2" Round Beehive (10)     | 25565B    | N25565B    |
|    | Challenger (10)           | 25569B    | N25569B    |
| A. | Bulls-Eye (10)            | 25570BC   | N25570BC   |
| B. | Bulls-Eye (10) ID Pattern | 25570BCID | N25570BCID |
|    | 3/4" Button (10)          | 25570GB   | N25570GB   |
|    | Fusion (10)               | 25571BC   | N25571BC   |
|    | M1 (8)                    | 25561M1   | N25561M1   |
|    | M3 (10)                   | 25564M3   | N25564M3   |
|    | M5 (10)                   | 25569M5   | N25569M5   |
|    | Mini (10)                 | 25569MN   | N25569MN   |



#### REPLACEMENT VISOR (2004 & NEWER)

|  |                           |          |           |
|--|---------------------------|----------|-----------|
|  | Blank (0)                 | 25540    | N25540    |
|  | Supernova (8)             | 25541    | N25541    |
|  | Crew (8)                  | 25543    | N25543    |
|  | 2" Round Flat (10)        | 25544B   | N25544B   |
|  | 2" Round Beehive (10)     | 25545B   | N25545B   |
|  | Challenger (10)           | 25549B   | N25549B   |
|  | Bulls-Eye (10)            | 25550B   | N25550B   |
|  | Bulls-Eye (10) ID Pattern | 25550BID | N25550BID |
|  | 3/4" Button (10)          | 25550GB  | N25550GB  |
|  | Fusion (10)               | 25551BC  | N25551BC  |
|  | M1 (8)                    | 25541M1  | N25541M1  |
|  | M3 (10)                   | 25544M3  | N25544M3  |
|  | M5 (10)                   | 25549M5  | N25549M5  |
|  | Mini (10)                 | 25549MN  | N25549MN  |




### FREIGHTLINER CENTURY / COLUMBIA CONDO / MID-ROOF VISORS

With 2 Side bolts per side. Add an "L" after your part number to order a Louvered Visor. Does not replace a stainless steel day cab visor. (Kit)

#### 17" DROP VISOR (2003 & EARLIER)

|    |                           |          |           |
|----|---------------------------|----------|-----------|
|    | Blank (0)                 | 25520    | N25520    |
| C. | Supernova (8)             | 25521    | N25521    |
|    | Crew (8)                  | 25523    | N25523    |
|    | 2" Round Flat (10)        | 25524B   | N25524B   |
|    | 2" Round Beehive (10)     | 25525B   | N25525B   |
|    | Challenger (10)           | 25529B   | N25529B   |
|    | Bulls-Eye (10)            | 25530B   | N25530B   |
| D. | Bulls-Eye (10) ID Pattern | 25530BID | N25530BID |
|    | 3/4" Button (10)          | 25530GB  | N25530GB  |
|    | Fusion (10)               | 25531BC  | N25531BC  |
|    | M1 (8)                    | 25521M1  | N25521M1  |
|    | M3 (10)                   | 25524M3  | N25524M3  |
|    | M5 (10)                   | 25529M5  | N25529M5  |
|    | Mini (10)                 | 25529MN  | N25529MN  |



See Image E for 3 Bolt Visor Example.

See Image F for 2 Bolt Visor Example.

Note: Some 2004 & Newer Freightliner trucks may also use 2 Bolt configuration.

#### REPLACEMENT VISOR (2003 & EARLIER)

|  |                           |          |           |
|--|---------------------------|----------|-----------|
|  | Blank (0)                 | 25500    | N25500    |
|  | Supernova (8)             | 25501    | N25501    |
|  | Crew (8)                  | 25503    | N25503    |
|  | 2" Round Flat (10)        | 25504B   | N25504B   |
|  | 2" Round Beehive (10)     | 25505B   | N25505B   |
|  | Challenger (10)           | 25509B   | N25509B   |
|  | Bulls-Eye (10)            | 25510B   | N25510B   |
|  | Bulls-Eye (10) ID Pattern | 25510BID | N25510BID |
|  | 3/4" Button (10)          | 25510GB  | N25510GB  |
|  | Fusion (10)               | 25511BC  | N25511BC  |
|  | M1 (8)                    | 25501M1  | N25501M1  |
|  | M3 (10)                   | 25504M3  | N25504M3  |
|  | M5 (10)                   | 25509M5  | N25509M5  |
|  | Mini (10)                 | 25509MN  | N25509MN  |





**CLASSIC / FLD FLAT TOP UNTIE VISORS**

Replaces factory stainless visor. If no existing visor or if replacing factory fiberglass visor you will also need Bracket Kit 25000-08 in addition to your visor. Add an "L" after your part number to order a louvered visor. [1995-2009] (Kit)

**CLASSIC / FLD FLAT TOP UNTIE DROP VISOR**

|                                |              |               |
|--------------------------------|--------------|---------------|
| <b>G.</b> Door Mounted Mirrors | <b>25004</b> | <b>N25004</b> |
| <b>H.</b> Cab Mounted Mirrors  | <b>25024</b> | <b>N25024</b> |

**BRACKET KITS**

If no existing visor or if replacing factory fiberglass visor you will need Bracket Kit 25000-08 in addition to above visors. Does not fit integral fit / car hauler. For integral flat top / car hauler, use **25000-08CH** below. (Kit)

|  |                   |                    |
|--|-------------------|--------------------|
| Fiberglass Visor Replacement Bracket Kit                                     | <b>25000-08</b>   | <b>N25000-08</b>   |
| Fiberglass Visor Replacement Bracket Kit Fits integral flat top / car hauler | <b>25000-08CH</b> | <b>N25000-08CH</b> |


**CLASSIC / FLD CONDO UNTIE DROP VISOR**

|                                  |                   |                    |
|----------------------------------|-------------------|--------------------|
| Blank (0)                        | <b>25320UT</b>    | <b>N25320UT</b>    |
| Supernova (8)                    | <b>25321UT</b>    | <b>N25321UT</b>    |
| Crew (8)                         | <b>25323UT</b>    | <b>N25323UT</b>    |
| <b>I.</b> 2" Round Flat (10)     | <b>25324UTB</b>   | <b>N25324UTB</b>   |
| 2" Round Beehive (10)            | <b>25325UTB</b>   | <b>N25325UTB</b>   |
| Challenger (10)                  | <b>25329UTB</b>   | <b>N25329UTB</b>   |
| Bulls-Eye (10)                   | <b>25330UTB</b>   | <b>N25330UTB</b>   |
| Bulls-Eye (10) <b>ID Pattern</b> | <b>25332UTBID</b> | <b>N25332UTBID</b> |
| 3/4" Button (10)                 | <b>25330UTGB</b>  | <b>N25330UTGB</b>  |
| Fusion (10)                      | <b>25331UTBC</b>  | <b>N25331UTBC</b>  |
| M1 (8)                           | <b>25321UTM1</b>  | <b>N25321UTM1</b>  |
| M3 (10)                          | <b>25324UTM3</b>  | <b>N25324UTM3</b>  |
| M5 (10)                          | <b>25329UTM5</b>  | <b>N25329UTM5</b>  |
| Mini (10)                        | <b>25329UTMN</b>  | <b>N25329UTMN</b>  |

**FREIGHTLINER CENTURY / COLUMBIA CONDO / MID-ROOF UNTIE VISORS**

Does not replace stainless steel day cab visor. **For trucks with 2 bolts per visor side.** (2003 & Earlier) (Kit)

|                                  |                   |                    |
|----------------------------------|-------------------|--------------------|
| Blank (0)                        | <b>25520UT</b>    | <b>N25520UT</b>    |
| Supernova (8)                    | <b>25521UT</b>    | <b>N25521UT</b>    |
| Crew (8)                         | <b>25523UT</b>    | <b>N25523UT</b>    |
| 2" Round Flat (10)               | <b>25524UTB</b>   | <b>N25524UTB</b>   |
| 2" Round Beehive (10)            | <b>25525UTB</b>   | <b>N25525UTB</b>   |
| Challenger (10)                  | <b>25529UTB</b>   | <b>N25529UTB</b>   |
| <b>J.</b> Bulls-Eye (10)         | <b>25530UTGB</b>  | <b>N25530UTGB</b>  |
| Bulls-Eye (10) <b>ID Pattern</b> | <b>25530UTBID</b> | <b>N25530UTBID</b> |
| 3/4" Button (10)                 | <b>25530UTB</b>   | <b>N25530UTB</b>   |
| Fusion (10)                      | <b>25531UTBC</b>  | <b>N25531UTBC</b>  |
| M1 (8)                           | <b>25521UTM1</b>  | <b>N25521UTM1</b>  |
| M3 (10)                          | <b>25524UTM3</b>  | <b>N25524UTM3</b>  |
| M5 (10)                          | <b>25529UTM5</b>  | <b>N25529UTM5</b>  |
| Mini (10)                        | <b>25529UTMN</b>  | <b>N25529UTMN</b>  |



See Image F Previous Page for 2 Bolt Visor Example.

**FREIGHTLINER CENTURY / COLUMBIA / CORONADO CONDO / MID-ROOF UNTIE VISORS**

Does not replace stainless steel day cab visor. **For trucks with 3 bolts per visor side.** (2004 & Newer) (Kit)

|                                  |                    |                     |
|----------------------------------|--------------------|---------------------|
| Blank (0)                        | <b>25560UT</b>     | <b>N25560UT</b>     |
| Supernova (8)                    | <b>25561UT</b>     | <b>N25561UT</b>     |
| Crew (8)                         | <b>25563UT</b>     | <b>N25563UT</b>     |
| 2" Round Flat (10)               | <b>25564UTB</b>    | <b>N25564UTB</b>    |
| 2" Round Beehive (10)            | <b>25565UTB</b>    | <b>N25565UTB</b>    |
| Challenger (10)                  | <b>25569UTB</b>    | <b>N25569UTB</b>    |
| <b>K.</b> Bulls-Eye (10)         | <b>25570UTBC</b>   | <b>N25570UTBC</b>   |
| Bulls-Eye (10) <b>ID Pattern</b> | <b>25570UTBCID</b> | <b>N25570UTBCID</b> |
| 3/4" Button (10)                 | <b>25570UTGB</b>   | <b>N25570UTGB</b>   |
| Fusion (10)                      | <b>25571UTBC</b>   | <b>N25571UTBC</b>   |
| M1 (8)                           | <b>25561UTM1</b>   | <b>N25561UTM1</b>   |
| M3 (10)                          | <b>25564UTM3</b>   | <b>N25564UTM3</b>   |
| M5 (10)                          | <b>25569UTM5</b>   | <b>N25569UTM5</b>   |
| Mini (10)                        | <b>25569UTMN</b>   | <b>N25569UTMN</b>   |



See Image E Previous Page for 3 Bolt Visor Example.

**N** \*The part numbers beginning with 'N' in the right-sided column designate 304 stainless material. 304 stainless has enhanced corrosion resistance.