

Freightliner Century/Columbia  
Replacement Visor  
2004 and newer

drill 1/2" holes for the  
outer brackets and install  
with supplied hardware

factory hardware  
will be used for  
center bracket

drill 1/2" holes for the  
outer brackets and install  
with supplied hardware

use factory  
hardware  
for ends

