


10.5" Drop Visor for 4000/7000/8000 Series DayCabs
Replaces Factory Stainless or Fiberglass Visor



It may be necessary to use sealant on light harness behind center bracket

55140-IN for use with part numbers 55140-55152